## VANDERBILT UNIVERSITY MEDICAL CENTER DIVISION OF TRAUMA AND SURGICAL CRITICAL CARE

## **IVC Filter Placement**

- 1. Indications for therapeutic Inferior Vena Cava filter (IVCF)
  - a. Pulmonary embolectomy for Pulmonary Embolism (PE)
  - b. PE or lower extremity DVT with
    - i. Contra-indication to anticoagulation (AC)
    - ii. Failure of AC
    - iii. Complication of AC
  - c. Propagation of thrombus while on adequate AC
- 2. Relative indications for therapeutic IVCF
  - a. PE or lower extremity DVT with significantly diminished pulmonary reserve
    - i. i.e., unable to suffer further impairment
- 3. Considerations for prophylactic IVCF
  - a. Spinal cord injury (paraplegia or quadriplegia)
  - b. IVC, iliac, or femoral venous ligation or repair
  - c. Severe pelvis fracture with lower extremity long-bone fracture
  - d. AIS head ≥3 with contraindication to anticoagulation
  - e. High risk for VTE (but no evidence of PE or DVT) with
    - i. Contra-indication to AC
      - ii. Failure of AC
      - iii. Complication of AC
- 4. TICU IVCF Placement Protocol
  - a. Preoperative considerations
    - i. One of the above indications
    - ii. Patient on a fluoroscopy compatible bed (trauma bed, although grid pattern is visible in image)
    - iii. Informed consent of patient or surrogate
    - iv. No significant renal impairment
    - v. No significant venous anomaly on trauma-gram
    - vi. Infra-renal IVC diameter 28mm or less
  - b. Device selection
    - i. Historically, device of choice has been femoral Cook Günther-Tulip
    - ii. Other options include Greenfield (permanent) or Bard G2 (removable)
  - c. Insertion protocol (bedside)
    - Once decision to place IVCF made and verified with procedure support nurse, radiology technicians notified to bring digital subtraction angiography (DSA) capable fluoroscopy machine to TICU
    - ii. Insertion sites in order of preference
      - 1. Right femoral vein (possible higher DVT risk)
      - 2. Right internal jugular vein (risk of PTX)
      - 3. Left femoral vein (potentially greater angulation and tilt)
      - 4. Left jugular (last resort)
      - 5. Smaller devices have been described as having been placed through brachial or axillary veins
    - iii. Trauma gram reviewed by proceduralists to estimate location of renal veins, anomalies, and IVC diameter
    - iv. 2-D and color Doppler U/S highly recommended to rule out insertion site thrombus and guide needle/wire placement
      - 1. Patent vessel
      - 2. Normal flow by color Doppler
    - v. See bedside surgery protocol regarding sterile precautions, sedation, and pre-procedure timeout
    - vi. After sterile prep and drape, vein is cannulated, and wire placed via Seldinger technique
    - vii. IVC venogram is prerequisite for placement and provides anatomic landmark

- 1. 5 Fr pigtail catheter with 1cm markers
- 2. 60cc Conray via Oz hand pump injection, visualized in real-time under digital subtraction angiography (during expiratory hold if ventilated)
- 3. Notation made of location of renal veins with respect to lumbar vertebrae as well as thrombus or anatomic anomaly
- viii. Device deployed under fluoroscopic guidance in an infrarenal location unless otherwise indicated
  - 1. Tip of device may be in the renal vein inflow
  - 2. Images saved of cava gram and post-deployment
- ix. Pressure held on insertion site and dressing applied
- x. Device lot numbers recorded in paper chart
- xi. EPIC procedure note written by proceduralist and signed by Attending
- xii. Wire precautions followed for subsequent venous access procedures
  - 1. Straight wire preferred > J-tip
- d. Notes, troubleshooting
  - i. Venogram inadequate
    - 1. Repeat venogram with the curled tip of the pigtail catheter just under estimated position of the renal veins
    - 2. Ensure that expiratory breath hold if patient ventilated
    - 3. DO NOT PROCEED IF VENOGRAM IS UNINTERPRETABLE
  - ii. Filter does not open
    - 1. Exceedingly rare
    - 2. Likely in accessory vessel (e.g. lumbar or gonadal vein)
    - 3. Repeat caval venogram or further imaging if any question
  - iii. Device malpositioned
    - 1. Consider consultation with interventional radiology or vascular surgery for assistance
    - 2. Suprarenal position typically does not require repositioning
  - iv. Provide follow-up for patients with removable IVCF and develop protocol for potential future removal, particularly for patients <50 yrs. of age
  - v. Both Cook and Bard jugular filters are completely deployed once they are unsheathed. The Cook device ensnares the filter until released, however, and must be released prior to removing the deployment mechanism.

Revised Feb 2019 Joey Curtis, RN Buddy Kopp, RN Brad Dennis, MD